

GENERAL NOTES FOR PERVIOUS SURFACING

1. Excluding construction of the facility itself, exposed treatment area subgrade shall be fenced to prohibit impacts from construction (including materials and equipment storage).
2. If unprotected soil has been exposed to rainfall, scarify the surface to a depth of 4 inches to restore infiltration capacity.
3. Contractor shall contact the approving agency 48 hours prior to placing geotextile fabric. The approving agency may call the engineer of record in advance of construction of this facility so construction observation may be performed to identify variations in the field that may affect design and verify proper construction.
4. Base rock shall be delivered clean and must pass visual inspection by Agency's inspection prior to placement.